

FIELD INSPECTION REPORT

Date of Inspection :	05-12-2020	District:	BANKA
Division :	BANKA-2	Length (km):	1.42
Name of the Road:	Bhagalpur Dumka Road to Khidde		
Scheme/Programme:	MAINTENANCE, M/R (old), 3054		
Package No.:		Road Id No.:	2070360080053
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓	S/U
b)	Condition of Surfacing	✓	S/U
c)	Riding Quality	✓	S/U
d)	Road Camber	✓	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓	Yes/No
g)	Compaction of flank/slope & raincuts if any	✓	Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	✓	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges		S/SRI/U N/A
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓	Yes/No
4.	Compliance History		
a)	Status of ATR's & any others	—	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

(Signature)
 05.12.2020

NAME: AJAY KUMAR

DESIGNATION: A.E.