FIELD INSPECTION REPORT

te of Insp	ection:	5/12/2020	District: Gay			
vision:		aya.	Length (km):	al the safe in the safe of	nations appear are miles over the survey of	
ame of th	e Road:		CE Under New Meet	Jevan	co Polity	
cheme/Pr	ogramme:	MAINTENAN	C LO	and the second s	anatonimina majorita a comminante de la communicación de la commun	
ackage N	0.:		Road Id No.:	distriction and street out and second		
Status of the Project: Work is a case of:		Ongoing/Completed/Under Maintenance				
		New Connectivity/Up gradation/ Maintenance		Remarks		
SI. No.		Paramete	ers to be checked		The state of the s	
1.	Pavement					
a)	Road Junction	on condition			S/U	
		Condition of Surfacing			S/U	
b)		And the state of t				
c)	Riding Quality				S/U	
d)	Road Camber					
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				Yes/No	
f)	Contraction Joints provided or not (CC Pavement)				Yes/No	
g)	Compaction of flank/slope & raincuts if any				Yes/No	
2.	Cross Dra	inage			C. Salaran	
a)	Condition	of head walls in I	Hume pipe culverts including its p	ainting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts				S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U		
3.	Road Fur			Actor 1		
a)	Whether stones/Par	sign boards/infovement road mark	rmatory/cautionary Board/km & kings are provided and maintained	200m	Yes/No	
4.	Complian	ace History	400			
a)	Status of	ATR's & any oth	zsurder Fender Prz	cess-		

Overall Rating

Satisfactory (S)		
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)		

(Signature) EE

NAME: Granshyam Rathak Rankay