

FIELD INSPECTION REPORT

Date of Inspection :		District: <u>MAWAZA</u>	
Division : <u>MAWAZA</u>		Length (km): <u>0.5 km</u>	
Name of the Road: <u>Nardigan road to Kahuwa Panna</u>			
Scheme/Programme:		<u>MAINTENANCE</u>	
Package No.:		Road Id No.:	
Status of the Project:		<u>Ongoing/Completed/Under Maintenance</u> <u>out of maintenance</u>	
Work is a case of:		<u>New Connectivity/Up gradation/ Maintenance</u>	
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		<u>SU N/A</u>
b)	Condition of surfacing		<u>SU N/A</u>
c)	Riding Quality		<u>SU N/A</u>
d)	Road Camber		<u>SU N/A</u>
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		<u>Yes/No N/A</u>
f)	Contraction Joints provided or not (CC Pavement)		<u>Yes/No</u>
g)	Compaction of flank/slope & raincuts if any		<u>Yes/No N/A</u>
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		<u>S/SRI N/A</u>
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		<u>S/SRI N/A</u>
c)	Condition of railings/slab/approach for Bridges		<u>S/SRI N/A</u>
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		<u>Yes/No NA</u>
4.	Compliance History		
a)	Status of ATRs & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Note:- The road is out of maintenance

S. S. S. S.
JE
(Signature) 04/12/2020

NAME: