

FIELD INSPECTION REPORT

Date of Inspection	5.12.20	District	Wardha
Division	Rajpura	Length (km)	2.956 km
Name of the Road	Amravati - Wardha Road (NH 181)		
Scheme/Programme	MAINTENANCE		
Package No.		Road Id No.	1852674
Status of the Project	Ongoing/Completed/Under Maintenance		
Work is a case of	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U NA	2.5.20 Wardha Phase II
b)	Condition of Surfacing	S/U NA	
c)	Riding Quality	S/U NA	
d)	Road Camber	S/U NA	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA	
g)	Compaction of flank/slope & raincuts if any	Yes/No NA	
2.	Gross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA	NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement	NA	

Overall Rating - NA

V. P. S.
5/12/20
(S. S.)