

FIELD INSPECTION REPORT

Date of Inspection : 05.12.2020	District: Nawada
Division : RAJAULI	Length (km): 3.200KM
Name of the Road: फतेहपुर गोबिन्दपुर रोड से पुरौली (जयपुर)	
Scheme/Programme: MAINTENANCE	NA
Package No.: NA	Road Id No.: NA
Status of the Project: Ongoing/Completed/Under Maintenance	NA
Work is a case of: New Connectivity/Up gradation/ Maintenance	NA

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U NA
b)	Condition of Surfacing	S/U NA
c)	Riding Quality	S/U NA
d)	Road Camber	S/U NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Yes/No NA
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No NA
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	NA
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Remarks - MR Road Patching job in person to Puralai Constructed by PMGSY-2 up-gradation Scheme.

05.12.2020
(Signature)

NAME: SUJIT KUMAR

DESIGNATION: JE/Gobindpur