

FIELD INSPECTION REPORT

Date of Inspection :	05/12/2020	District :	BHAHALPUR
Division :	R.W.D Works Div. Nangachhia	Length (km) :	0.750 KM
Name of the Road :	PWD Road Babhangama to Kaji Tola		
Scheme/Programme :	Maintenance New Maintenance Policy 2018		
Package No. :		Road Id No. :	
Status of the Project :	Ongoing/Completed/Under Maintenance <u>Ongoing</u>		
Work is a case of :	New Connectivity/Up gradation/Maintenance <u>Maintenance</u>		
Sl. No.	Parameteres to be checked	Remarks	
1	Pavement <u>Work not started</u>		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Road Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culvert including its painting.	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3	Cross Drainage		
a)	Whether sign boards/informatory/cautionary Boards/ km & 200m stones/Pavements roads marking are provided and maintained. <u>Informatory Board fixed at site.</u>	Yes/No	
4	Compliance History		
a)	Status of ATR's & any others	No	

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Narinder Kumar

DESIGNATION: Assistant Engineer

05/12/2020

सहायक अभियंता
(Signature)

कार्य अवर प्रमंडल, बिहपुर