

FIELD INSPECTION REPORT

Inspection 05/12/20

District : Bhagalpur

Division : Bhagalpur

Length (Km): 3.15

Name of the Road : NH-80 Tilakpur To Maheshi Chowk.

Scheme / Programme : MAINTENANCE ~~C.S. process~~

Package No. : group-17 Road Id No. : 20703202077

Status of the Project : Ongoing / Completed / Under Maintenance C.S. process

Work is a case of : New Connectivity / Up gradation / Maintenance

SL. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S / U
b)	Condition of Surfacing	S / U
c)	Riding Quality	S / U
d)	Road Camber	S / U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No
f)	Contraction Joints provided or not (CC Pavement)	Yes / No
g)	Compaction of flank/slope & raincuts if any	Yes / No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S / SRI / U
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S / SRI / U
c)	Condition of railings/slab/approach for Bridges	S / SRI / U
3.	Road Furniture	
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No
4.	Compliance History	
a)	Status of ATR's & any others	
Overall Rating: A+A is given & This road is in under repair process.		
	Satisfactory (S)	N/A
	Satisfactory but requires Improvement (SRI)	
	Unsatisfactory (U)	

NAME:

Radha Raman Singh.

DESIGNATION:

A.E

(Signature)

05/12/20
AE