

FIELD INSPECTION REPORT

(Black - Jagdishpur)

Date of Inspection :	05/12/2020	District :	Bhagalpur
Division :	Bhagalpur	Length (Km) :	2.50 Km.
Name of the Road :	Railway line Makasapur to Miranchak.		
Scheme / Programme :	MAINTENANCE (MR 010)		
Package No. :		Road Id No. :	20703208103
Status of the Project:	Ongoing / Completed / Under Maintenance		
Work is a case of :	New Connectivity / Up gradation / Maintenance		
SL. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S / U	NA
b)	Condition of Surfacing	S / U	
c)	Riding Quality	S / U	
d)	Road Camber	S / U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No	NA
f)	Contraction Joints provided or not (CC Pavement)	Yes / No	
g)	Cmpaction of flank/slope & raincuts if any	Yes / No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S / SRI / U	NA
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S / SRI / U	
c)	Condition of railings/slab/approach for Bridges	S / SRI / U	
3.	Road Furniture		
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No	NA
4.	Compliance History		
a)	Status of ATR's & any others	NA	
Overall Rating :			
	Satisfactory (S)		
	Satisfactory but requires Improvement (SRI)		
	Unsatisfactory (U)	NA	

Note: This road is taken in New Maintenance Policy 2018 and it is in tender process at present.

NAME: Lado Raman Singh
DESIGNATION: (Assistant Engineer)

[Signature]
05/12/20
J.E.

[Signature]
05/12/20
Signature AR