

FIELD INSPECTION REPORT

(Block - Shahkunda)

Date of Inspection :	05/12/2020	District : Bhagalpur
Division : Bhagalpur	Length (Km) :	1.560 Km.
Name of the Road :	Daniaapur (Hayanchak) to Harnathpur via Chandrang	
Scheme / Programme :	MAINTENANCE (old MR)	
Package No. :	Road Id No. :	20703208109
Status of the Project :	Ongoing / Completed / Under Maintenance	
Work is a case of :	New Connectivity / Up gradation / Maintenance	

SL. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S/U
f)	Contraction Joints provided or not (CC Pavement)	Yes / No
g)	Compaction of flank/slope & raincuts if any	Yes / No
2.	Cross Drainage	Yes / No
a)	Condition of head walls in Hume pipe culverts including its painting	S / SRI / U
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S / SRI / U
c)	Condition of railings/slab/approach for Bridges	S / SRI / U
3.	Road Furniture	S / SRI / U
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No
4.	Compliance History	
a)	Status of ATR's & any others	
Overall Rating :		NA
	Satisfactory (S)	
	Satisfactory but requires Improvement (SRI)	
	Unsatisfactory (U)	

NOTE - It has been taken in New Maintenance Policy 2018 & this road is in tender process at present.

NAME: Radha Kumar Singh
DESIGNATION: Assistant Engineer.

(Signature)

[Signature]
05/12/2020
AE