

FIELD INSPECTION REPORT

(Block - Shahkunda)

Date of Inspection :	04/12/2020	District : Bhagalpur
Division : Bhagalpur		Length (Km) : 1.50 Km
Name of the Road :	Kiranpur Madarsa More to Rasulga Village	
Scheme / Programme :	MAINTENANCE (Old MR)	
Package No. :		Road Id No. : 2070320 8208
Status of the Project:	Ongoing / Completed / Under Maintenance	
Work is a case of :	New Connectivity / Up gradation / Maintenance	
SL. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S / U
b)	Condition of Surfacing	S / U
c)	Riding Quality	S / U
d)	Road Camber	S / U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No
f)	Contraction Joints provided or not (CC Pavement)	Yes / No
g)	Cmpaction of flank/slope & raincuts if any	Yes / No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S / SRI / U
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S / SRI / U
c)	Condition of railings/slab/approach for Bridges	S / SRI / U
3.	Road Furniture	
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No
4.	Compliance History	
a)	Status of ATR's & any others	NR
Overall Rating :		
	Satisfactory (S)	
	Satisfactory but requires Improvement (SRI)	
	Unsatisfactory (U)	

Note: This road has been in New Maintenance Policy 2018 & road work is ongoing at present.

NAME: Radha Raman Singh
DESIGNATION: Assistant Engineer

Signature
04/12/20
AE