

FIELD INSPECTION REPORT

Inspection:	District Bhagalpur		
Division: Bhagalpur	Length (Km): 2.00 km.		
Name of the Road:	NH-30 Champa Nala pnd to Raghapur		
Scheme / Programme:	MAINTENANCE		
Package No.:	Road Id No.:		
Status of the Project:	Ongoing / Completed / Under Maintenance		
Work is a case of:	New Connectivity / Up gradation / Maintenance <i>Double Entry</i>		
SL. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S / U	<i>N.A.</i>
b)	Condition of Surfacing	S / U	
c)	Riding Quality	S / U	
d)	Road Camber	S / U	
e)	Whether free from defects such as visible cracks, exposed aggregate in case of CC Pavement	Yes / No	
f)	Construction joints provided or not (CC Pavement)	Yes / No	<i>N.A.</i>
g)	Compaction of subgrade & minimum of any	Yes / No	
2.	Cross Drainage		
a)	Condition of head walls in stone pipe culverts including its painting	S / SR1 / U	<i>N.A.</i>
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S / SR1 / U	
c)	Condition of cuttings/slabs/approach for Bridges	S / SR1 / U	
3.	Road Furniture		
a)	Whether sign boards / informative / cautionary Board / Km & 200m station / Pavement mark markings are provided and maintained.	Yes / No	
4.	Compliance History		
a)	Status of ATR's & any others		
Overall Rating <i>This Road is Double Entry</i>			
	Satisfactory (S)		
	Satisfactory but requires Improvement (SR1)		
	Unsatisfactory (U)		

NAME: *Lakshman pd. Yadav*

DESIGNATION: *J.C.*

(Signature)

Ashmay
04/12/2020
J.C.