

FIELD INSPECTION REPORT

(Block - Shahkud)

Date of Inspection : 03/12/2020		District : Bhagalpur	
Division : Bhagalpur		Length (Km) : 0.230 Km	
Name of the Road : S.H. Road Bhagalpur Bansi Road to Angari			
Scheme / Programme : MAINTENANCE		(old MR)	
Package No. :		Road Id No. : 20703208211	
Status of the Project : Ongoing / Completed / Under Maintenance			
Work is a case of : New Connectivity / Up gradation / Maintenance			
SL. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S / U	NA
b)	Condition of Surfacing	S / U	
c)	Riding Quality	S / U	
d)	Road Camber	S / U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No	NA
f)	Contraction Joints provided or not (CC Pavement)	Yes / No	
g)	Cmpaction of flank/slope & raincuts if any	Yes / No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S / SRI / U	NA
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S / SRI / U	
c)	Condition of railings/slab/approach for Bridges	S / SRI / U	
3.	Road Furniture		
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No	NA
4.	Compliance History		
a)	Status of ATR's & any others	NA	
Overall Rating :			
	Satisfactory (S)	NA	
	Satisfactory but requires Improvement (SRI)		
	Unsatisfactory (U)		

Note: This road has been taken in New Maintenance Policy 2018 & road work is progress at present.

NAME : Rakesh Kumar Singh
DESIGNATION : Assistant Engineer.

Signature
03/12/2020
AR