

FIELD INSPECTION REPORT		
Date of Inspection :	05/12/2020	District : BHANALPUR
Division :	RWD WORKS DIV. NANGAETHA	Length (km) : 1.600 Km
Name of the Road :	Railway Road Bihpur to Yadav Tola Bihampur via Hospital	
Scheme/Programme :	Maintenance New Maintenance Policy 2018	
Package No. :		Road Id No. :
Status of the Project :	Ongoing/Completed/Under Maintenance	Ongoing
Work is a case of :	New Connectivity/Up gradation/Maintenance	maintenance
Sl. No.	Parameters to be checked	Remarks
1	Pavement	work in progress
a)	Road Junction condition	S/U
b)	Condition of Surfacing	Patch Pot filled by WBM
c)	Road Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A
f)	Contraction Joints provided or not (CC Pavement)	N/A
g)	Compaction of flank/slope & raincuts if any	Earthwork in progress in flank
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culvert including its painting.	N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	N/A
c)	Condition of railings/slab/approach for Bridges	N/A
3	Cross Drainage	
a)	Whether sign boards/informatory/cautionary Boards/ km & 200m stones/Pavements roads marking are provided and maintained.	Informatory Board fixed at Site.
4	Compliance History	
a)	Status of ATR's & any others	No.

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME : VIKASH KUMAR

DESIGNATION : JUNIOR ENGINEER

Vikash Kumar
(Signature)
Work Section Bihpur