

FIELD INSPECTION REPORT

(Block - Jagdispur)

Date of Inspection :	05/12/2020	District :	Bhagalpur
Division :	Bhagalpur	Length (Km) :	1.00 Km
Name of the Road :	Shahkunda Pulwaris RKO Road ke Yamshed to Bhrakimpur via chare Bargadda.		
Scheme / Programme :	MAINTENANCE		
Package No. :	Group IV - 09	Road Id No. :	20703201054
Status of the Project :	Ongoing / Completed / Under Maintenance		
Work is a case of :	New Connectivity / Up gradation / Maintenance		
SL. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S / U	S
b)	Condition of Surfacing	S / U	S
c)	Riding Quality	S / U	S
d)	Road Camber	S / U	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No	Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes / No	Yes
g)	Compaction of flank/slope & raincuts if any	Yes / No	Yes
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S / SRI / U	S
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S / SRI / U	S
c)	Condition of railings/slab/approach for Bridges	S / SRI / U	S
3.	Road Furniture		
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No	Yes
4.	Compliance History		
a)	Status of ATR's & any others	NO	
Overall Rating :			
	Satisfactory (S)	S	
	Satisfactory but requires Improvement (SRI)	—	
	Unsatisfactory (U)	—	

NAME :

Radda Raman Singh

DESIGNATION :

Assistant Engineer

(Signature)

05/12/2020
AE