

FIELD INSPECTION REPORT

Date of Inspection :	05/12/2020	District : BHAWALPUR
Division :	NAVHACHHIA	Length (km) : 4.50 km
Name of the Road :	Mathurapur Bazar to Raipur Hanjan Tola.	
Scheme/Programme :	Maintenance New Maintenance Policy - 2018	
Package No. :	MR-N/2019-20 NAVHACHHIA/11	Road Id No. :
Status of the Project :	Ongoing/Completed/Under Maintenance	
Work is a case of :	New Connectivity/Up gradation/Maintenance	
Sl. No.	Parameteres to be checked	Remarks
1	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Road Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culvert including its painting.	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3	Cross Drainage	
a)	Whether sign boards/informatory/cautionary Boards/ km & 200m stones/Pavements roads marking are provided and maintained. <i>informatory Board has been fixed out life</i>	Yes/No
4	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :	Satisfactory (S)	NA
	Satisfactory but requires Improvement (SRI)	
	Unsatisfactory (U)	

Remarks - Above work not started.

Narendra Kumar
05/12/2020
(Signature)

NAME: Narendra Kumar
DESIGNATION: Assistant Engineer

सहायक अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रमंडल नारायणपुर