

FIELD INSPECTION REPORT

4

Inspection: 05/12/20	District: Bhagalpur
Location: Bhagalpur	Length (Km): 2.0
Name of the Road: NH-80 to Makandpur	
Scheme / Programme: MAINTENANCE	
Package No.: group-18	Road Id No.: 20703301029
Status of the Project: Ongoing / Completed / Under Maintenance C-5. process.	
Work is a case of: New Connectivity / Up gradation / Maintenance	

SL. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S / U
b)	Condition of Surfacing	S / U
c)	Riding Quality	S / U
d)	Road Camber	S / U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes / No
g)	Cmpaction of flank/slope & raincuts if any	Yes / No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S / SRI / U
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S / SRI / U
c)	Condition of railings/slab/approach for Bridges	S / SRI / U
3.	Road Furniture	
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No
4.	Compliance History	
a)	Status of ATR's & any others	
Overall Rating: A.A given & This road is in under tender process.		
	Satisfactory (S)	
	Satisfactory but requires Improvement (SRI)	N/A
	Unsatisfactory (U)	

NAME:

Radha Raman Singh

DESIGNATION:

A.E

(Signature)

05/12/20
AB