FIELD INSPECTION REPORT

Date of Inspection: 06.12.2020		06.12.2020	District: Banka	
Division: 890Kg-1			Length (km): 2, 4,	
Name of	the Road: Bo	nka-Belhan Road	- Mahanaladul.	
Scheme/	Programme:	MAINTENANCE	4	
Package	No .: RM/BI	4/BAN/19/00/2	Road Id No.: 2070350:	2029
Status of	the Project:	Ongoing/Completed/U	nder Maintenance	
	a case of:	New Connectivity/Up	gradation/ Maintenance	,
Sl. No.		Parameters to be	checked	Remarks
1.	Pavement			
a)	Road Junction condition			S/U o
b)	Condition of	Surfacing		S/U on
3)	Riding Quali	ıy ·		S/U 0
d)	Road Camber			S/U 0
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. Yes/No			Yes/No
1)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drain	age		
a)	Condition of head walls in Hume pipe culverts including its painting			'S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)		n boards/informatory/ca	utionary Board/km & 200m	Yes/No

Overall Rating :

4.

a)

Compliance History

Status of ATR's & any others

Satisfactory (S)	salistactory(s).
Satisfactory but requires Improvement (SRI)	Alskind 1823.
Unsatisfactory (U)	

(Signature)

NAME: PRITAM KUMAR

DESIGNATION: A-E