

FIELD INSPECTION REPORT

Date of Inspection : 04.12.2020 District: Banka
 Division : Banka-2 Length (km): 2.492
 Name of the Road: BWP Dura Road to Begduma
 Scheme/Programme: MAINTENANCE
 Package No.: RM/BA/BAN/00520/000 Road Id No.: 20703502056
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Upgradation/Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road surface condition	S/U ongoing
b)	Condition of sub-grade	S/U ongoing
c)	Condition of base	S/U ongoing
d)	Road Camber	S/U ongoing
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No N.A
f)	Contractor to be provided or not (CC Pavement)	Yes/No N.A
g)	Condition of flank/slope & raincuts if any	Yes/No Ongoing
2.	Cross Drainage	
a)	Condition of head walls in stone culverts including its painting	S/SRTI Ongoing
b)	Condition of Abutment & Wing walls Slab in RCC culverts	S/SRTI Ongoing
c)	Condition of railings Slope approach for Bridges	S/SRTI N.A
3.	Road Furniture	
	Whether sign boards informative/cautionary Board/1m & 200m stones Pavement road markings are provided and maintained	✓ Yes
4.	Compliance History	
	State of A.R's & any others	

Overall Rating

Satisfactory (S) (S)

Satisfactory but requires improvement (SRI)

Unsatisfactory (U)

Satisfactory (S)

PRITAM KOMAR

DESIGNATION: A.E

Pratim
04.12.2020
(Signature)