

FIELD INSPECTION REPORT

Date of Inspection :	05/12/2020	District: Banka
Division :	Banka-1	Length (km): 6.50 KM.
Name of the Road:	Banda P.M. Road to Banda P.M. Road	
Scheme/Programme:	MAINTENANCE	
Package No.:	RM/BA/BAN/2.0/0002	Road Id No.: NEA 19 000315
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U ongoing
b)	Condition of Surfacing	S/U ongoing
c)	Riding Quality	S/U ongoing
d)	Road Camber	S/U ongoing
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N.A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N.A
g)	Compaction of flank/slope & raincuts if any	Yes/No ongoing
2.	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ongoing
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U ongoing
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N.A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ongoing
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	Satisfactory
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Phil
05/12/2020
(Signature)

NAME: Ashok Kumar Sinha

DESIGNATION: Junior Engineer