

FIELD INSPECTION REPORT

Date of Inspection : 05/12/2020		District: Samardipura	
Division : Samardipura (Marsiyagaj)		Length (km): 0.85 km	
Name of the Road: MDR TO 2 to Manigadipura			
Scheme/Programme: MAINTENANCE			
Package No.:		Road Id No.: NEA220001274	
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of: New Connectivity/Up gradation/ Maintenance			
Sl. No.	Parameters to be checked	Remarks	
1. Pavement			
a)	Road Junction condition	✓	
b)	Condition of Surfacing	✓	
c)	Riding Quality	✓	
d)	Road Camber	✓	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	NA -
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	NA -
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2. Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting	S/SR/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U	
c)	Condition of railings/slab/approach for Bridges	S/SR/U	NA
3. Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4. Compliance History			
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	Satisfactory
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: RISHU RAJ

DESIGNATION: JE-Marsiyagaj

05/12/2020
(Signature)