


Defect Inspection: 3/12/20
 Division: Belthar
 District: West Kamrup
 Length: 35
 Name of the Road: Tumkoria to Malhariga
 Scheme/Programme: MAINTENANCE
 Package No.: MR-N/13-20 Belthar 02 Road No.: NEA2200U135
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No H/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No H/A
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in stone pipe culverts including its painting	S/SRI/U H/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U H/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U H/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


 (Signature) 3/12/20

NAME: R. H. B. Prasad

DESIGNATION: J E