

FIELD INSPECTION REPORT

Date of Inspection : _____	District: <u>Lakhisarai</u>
Division : <u>Lakhisarai</u>	Length (km): <u>200 KM</u>
Name of the Road: <u>Bannu Bagicha to Sidhaul</u>	
Scheme/Programme: <u>MAINTENANCE</u>	
Package No.: _____	Road Id No.: <u>NEA220001370</u>
Status of the Project: <u>Ongoing/Completed/Under Maintenance</u>	
Work is a case of: <u>New Connectivity/Up gradation/ Maintenance</u>	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

This Road is in Technical Bid.

NAME: Anisur Rahman

DESIGNATION: Executive Engineer

(Signature)
04/12/2020
ग्रामीण कार्य विभाग कार्यालय
लखीसराय