FIELD INSPECTION REPORT

ate of Inspection:			District: Lakwsadai	
ivision :	Lakhisa	rai	Length (km): 7-55 KM	and the state of t
lame of t		023 to Sriv	ngi Rishi Ashram	
	Programme:	MAINTENANCE		1410
ackage]			Road Id No.: NEA22000	1469
	the Project:	Ongoing/Completed	/Under Maintenance	
		LANCE CONTRACTOR OF THE SECOND STATE OF THE SE	Jp gradation/ Maintenance be checked Remarks	
Sl. No.	Parameters to be checked			Kemarks
A_{n}	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.7	Compliance History			
a)	Status of AT	R's & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

This Road is in Retender.

NAME: Anisur Rahman

DESIGNATION: Executive Engineer

(Sक्षाज्यामके अभियन्ता ग्रामीण कार्य विभाग कार्य प्रमहल लखीसराव