

FIELD INSPECTION REPORT

DATE OF INSPECTION:	05.12.2020	DISTRICT:	PURNA.
DIVISION:	PRANDANA	LENGTH:	10.00 KM
NAME OF THE ROAD:	Benipuramgha Kulkola via Janyakithan		
SCHEME/PROGRAMME:	MAINTENANCE		
PACKAGE No:	ROAD ID No.:		
STATUS OF THE PROJECT:	ONGOING/COMPLETED/UNDER MAINTENANCE		
WORK IS A CASE OF:	NEW CONNECTIVITY/UP GRADATION/MAINTENANCE		
SLNO	PARAMETERS TO BE CHECKED	REMARKS	
1	PAVEMENT		
A	ROAD JUNCTION CONDITION	/	
B	CONDITION TO SURFACING	/	
C	RIDING QUALITY	/	
D	ROAD CAMBER	/	
E	WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE OF CC PAVEMENT	/	
F	CONTRACTION JOINTS PROVIDED OR NOT(CC PAVEMENT)	/	
G	COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY	/	
2	CROSS DRAINAGE		
A	CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS PAINTING	/	
B	CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS	/	
C	CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES	/	
3	ROAD FURNITURE		
A	WHETHER SIGN BOARDS /INFORMATORY BOARD/ KM & 200 M STONES/PAVEMENT ROAD MARKING ARE PROVIDED AND MAINTAINED	S	
4	COMPLIANCE HISTORY		
A	STATUS OF ATR's & ANY OTHERS	/	
OVERALL RATING			
	SATISFACTORY(S)	S	
	SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)	/	
	UNSATISFACTORY(U)	/	

NAME: PRAMOD KUMAR
DESIGNATION: JUNIOR-ENGINEER

P. Kumar
05-12-2020 -
SIGNATURE