

## FIELD INSPECTION REPORT

| Date of Inspection: 04.12.2020.                    |                                                                                                                     | District:- Sitamarhi.                      |
|----------------------------------------------------|---------------------------------------------------------------------------------------------------------------------|--------------------------------------------|
| Division:-RWD, Works Div. Pupri.                   |                                                                                                                     | Length (km):- 1.850 K.m.                   |
| Name of the Road:- HARIHARPUR To BHIMA MAKLESHWAR. |                                                                                                                     |                                            |
| Scheme/Programme:-                                 |                                                                                                                     | MAINTENANCE                                |
| Package No.:- MR-N/19-20 pupri/13                  |                                                                                                                     | Road Id No.: NEA220001933                  |
| Status of the Project:                             |                                                                                                                     | Ongoing/Completed/Under Maintenance        |
| Work is a case of:                                 |                                                                                                                     | New Connectivity/Up gradation/ Maintenance |
| Sl. No.                                            | Parameters to be checked                                                                                            | Remarks                                    |
| 1.                                                 | Pavement (Work Issued Just Before Blockage) In Agreement process.                                                   |                                            |
| a)                                                 | Road Junction condition                                                                                             | S/U                                        |
| b)                                                 | Condition of Surfacing                                                                                              | S/U                                        |
| c)                                                 | Riding Quality                                                                                                      | S/U                                        |
| d)                                                 | Road Camber                                                                                                         | S/U                                        |
| e)                                                 | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement                         | Yes/No                                     |
| f)                                                 | Contraction Joints provided or not (CC Pavement)                                                                    | Yes/No                                     |
| g)                                                 | Compaction of flank/slope & raincuts if any                                                                         | Yes/No                                     |
| 2.                                                 | Cross Drainage                                                                                                      |                                            |
| a)                                                 | Condition of head walls in Hume pipe culverts including its painting                                                | S/SRI/U                                    |
| b)                                                 | Condition of Abutments & Wing walls, Slab in RCC culverts                                                           | S/SRI/U                                    |
| c)                                                 | Condition of railing/slab/approach for bridges                                                                      | S/SRI/U                                    |
| 3.                                                 | Road Furniture                                                                                                      |                                            |
| a)                                                 | Whether sing board/informatory/cautionary Board/ Km & 200m stones/Pavement road marking are provided and maintained | Yes/No                                     |
| 4.                                                 | Compliance History                                                                                                  |                                            |
| a)                                                 | Status of ATR's & any others                                                                                        |                                            |


N.A.

Overall Rating : N/A

|                                             |  |
|---------------------------------------------|--|
| Satisfactory (S)                            |  |
| Satisfactory but requires Improvement (SRI) |  |
| Unsatisfactory (U)                          |  |

Name:- RAMBABU

DESIGNATION:- E.E., Rwd., Pupri

  
 (Signature) 04.12.20