

FIELD INSPECTION REPORT

Date of Inspection :	06-12-2020	District :	
Division :		Length (km):	1.10 KM
Name of the Road:	Kumhari Barai tola — Kamchampur		
Scheme Programme:	MAINTENANCE		
Package No.:	MR-N/19-20/Mahm/05	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance (Work not started)		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	N.A S/U	
b)	Condition of Surfacing	N.A S/U	
c)	Riding Quality	N.A S/U	
d)	Road Camber	N.A S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N.A Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	N.A Yes/No	
g)	Compaction of flank/slope & raincuts if any	N.A Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	N.A S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N.A S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	N.A S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	N.A Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	No	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Work not started

Shafiqur.
6/12/20
(Signature)

NAME: Shailendra Kumar.

DESIGNATION: I.E RWD, Bidupur.