

FIELD INSPECTION REPORT

Date of Inspection: 06-12-2020 District: Vaishali
 Division: Matman Length (km): 3.00 km
 Name of the Road: Gopkhula - parapur Sankham Stham
 Scheme Programme: MAINTENANCE
 Package No.: MR-4/13-20/matman/04 Road Id No.:
 Status of the Project: Ongoing/Completed/Under Maintenance (Work not started)
 Work is a case of: New Connectivity/Under Addition/Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	N.A S/U
b)	Condition of Surfacing	N.A S/U
c)	Riding Quality	N.A S/U
d)	Road Camber	N.A S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N.A Yes/No
f)	Contraction Joints provided or not (CC Pavement)	N.A Yes/No
g)	Compaction of flank/slope & raincuts if any	N.A Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	N.A S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N.A S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N.A S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	N.A Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Work not started

06/12/2020

(Signature)

NAME: SHROBON KUMAR PROSAD

DESIGNATION: A.E.R.W.D.