

FIELD INSPECTION REPORT

Date of Inspection : 05-12-2020	District: Vaishali
Division : Mah nag.	Length (km): 3.0 K.M
Name of the Road: Katharia Baram to Andharaga.	
Scheme/Programme: MAINTENANCE ✓	
Package No.: MR-N/19-20/Mah nag/03	Road Id No.: N.A
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. N.A	Yes/No
f)	Contraction Joints provided or not (CC Pavement) N.A	Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained under work.	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

work in progress

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature) 5/12/20

NAME:

Shailendra Kumar.

DESIGNATION:

J.E RWD, Bidupur.