

FIELD INSPECTION REPORT

Date of Inspection : 06-12-20		District: Varanasi
Division : Mahara		Length (km): 2.25 km
Name of the Road: Kanchari Chowk - Haldipur - Gondaria Road		
Scheme/Programme: MAINTENANCE		
Package No.: MR-N/19-23/Mahara-05	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance (Completed)	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	N/A SU
b)	Condition of Surfacing	N/A SU
c)	Riding Quality	N/A SU
d)	Road Camber	N/A SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A Yes/No
f)	Contraction Joints provided or not (CC Pavement)	N/A Yes/No
g)	Compaction of flank/slope & rainouts if any	N/A Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N/A S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 300m stones/Pavement road markings are provided and maintained	N/A Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	Work not Started
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)
6/12/20

NAME: Shailendra Kumar
DESIGNATION: J-E RWD, Bidepur