## FIELD INSPECTION REPORT

	FIELD INSPECTION	ON REPORT	
	nspection: 4/12/20 Di	strict: Vaishali	
Division: Mahua:			
Name of the Road: Rollo wood Principal Laborat Chitrach			igher
Scheme/	rogramme: MAINTENANCE	261011	
Package		oad Id No.:	
	the Project: Ongoing/Completed/Un	der Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance		Remarks	
Sl. No.	Parameters to be checked Remarks		Kemaria
1.	Pavement		
a)	Road Junction condition		S/U
			S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		
e)	whether free from defects such as visited		Yes/No
	aggregates in case of CC Pavement.  Yes/		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		103/110
2.	Cross Drainage	The same of the sa	or Herrisal was
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
J.	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained  Yes/No		
a)			
4.	Compliance History		September 1
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Agreement Newt done.

1115.50

(Signature)

NAME:

**DESIGNATION:**