FIELD INSPECTION REPORT

-		VIELD INSPEC	TION TO THE TOTAL THE TOTAL TO THE TOTAL TOT		
Date of I	nspection:	5.12.20	District: Vai Lati		
MAINIA.			Length (km): 1.2 0		
Name of	the Road:		Lar Parsaunia red		
Scheme/1	rogramme:	MAINTENANCE	Work not start		
Package	No.:	Q	Road Id No.:		
Status of	the Project:	Ongoing/Completed			
the second second	a case of:		p gradation/ Maintenance	Carlos de la carlo	
Sl. No.		Parameters to		Remarks	
1.	Pavement				
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Draina	ge	40.74		
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes/No				
4.	Compliance History				
a)	Status of ATR	's & any others			

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Agreement Done Work not Started.

(Signature)

14. A

NAME:

DESIGNATION: कार्यपालक अभियंता ग्रामीण कार्य विभाग कार्य प्रमंडल, महुआ