


FIELD INSPECTION REPORT

Date of Inspection:	05.12.2020	District:	Darbhanga.
Division:	RWD W(Div) Darbhanga-2	Length(Km):	13.6 Km
Name of Road:	Bariaul Khatiya Kaligaon to Bhatwara road.		
Scheme/Programme:	Maintenance MR-3054 (New Maint. Policy-2018).		
Package No.	—	Road Id No.	—
Status of the Project:	Ongoing/Completed/ Under Maintenance —		
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓		

S No.	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction condition	S/U NA
b)	Condition of Surfacing	S/U NA
c)	Riding Quality	S/U NA
d)	Road Camber	S/U NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank /slope & raincuts if any	Yes/No NA
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing walls , Slabs in RCC culverts	S/SRI/U NA
c)	Condition of railing /slabs/ approach for Bridges	S/SRI/U NA
3	Road Furniture	
a)	Whethersign boards/ informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained	Yes/No NA
3	Compliance History	
a)	Status of ATR's & any others	— NA

Overall Rating:

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


 (Signature)

Name:

Designation: