

FIELD INSPECTION REPORT

Date of Inspection:	06.12.2020.	District:	Dibrugarh.
Division:	INDONESIA (DIV) Dibrugarh 2	Length(Km):	2.61 km.
Name of Road:	L053- Kathuria.		
Scheme/Programme:	Maintenance New Maint. policy - 2018, Head-2014		
Package No.	—	Road Id No.	—
Status of the Project:	Ongoing/Completed/ Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/ Maintenance ✓		

S No.	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction condition	S/U NA
b)	Condition of Surfacing	S/U NA
c)	Riding Quality	S/U NA
d)	Road Camber	S/U NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank /slope & raincuts if any	Yes/No NA
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing walls , Slabs in RCC culverts	S/SRI/U NA
c)	Condition of railing /slabs/ approach for Bridges	S/SRI/U NA
3	Road Furniture	
a)	Whether sign boards/ informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained	Yes/No NA
3	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating:

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

Name: KUMAR CHANDRAS

Designation: ASST. ENGINEER.