

FIELD INSPECTION REPORT

Date of Inspection: 5/12/20 District: Vaidhali
 Division: Hapur Length (km): 1.10 km
 Name of the Road: Barhatia Jagarpur to Hanbali
 Scheme/Programme: MAINTENANCE NR
 Package No. Road Id No.
 Status of the Project: ☒ Ongoing ☐ Completed ☐ Under Maintenance
 Work is a case of: ☒ New Connectivity ☐ Up gradation ☐ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S1
b)	Condition of Surfacing	S1
c)	Riding Quality	S1
d)	Road Camber	S1
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	work in Progress (lot filling)

Overall Rating :

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—


 (Signature)

NAME:

DESIGNATION: