

FIELD INSPECTION REPORT

Date of Inspection : 5/12/20	District: Vainhalli
Division : Mahua	Length (km): 2.75 km
Name of the Road: Chakwali-Haripurjad (L30) CH 0.0 to 2.75 km	
Scheme/Programme: MAINTENANCE	Work not started
Package No.: 10	Road Id No.:
Status of the Project: ☒ Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	Remarks
Sl. No.	Parameters to be checked
1.	Pavement
a)	Road Junction condition
b)	Condition of Surfacing
c)	Riding Quality
d)	Road Camber
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.
f)	Contraction Joints provided or not (CC Pavement)
g)	Compaction of flank/slope & raincuts if any
2.	Cross Drainage
a)	Condition of head walls in Hume pipe culverts including its painting
b)	Condition of Abutment & Wing walls, Slab in RCC culverts
c)	Condition of railings/slab/approach for Bridges
3.	Road Furniture
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained
4.	Compliance History
a)	Status of ATR's & any others

N/A

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Agreement Done.
Work not started.

5/12/20
J.D.

5/12/20
A.E.

(Signature)

NAME:

DESIGNATION:

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, महाराष्ट्र