

## FIELD INSPECTION REPORT

<b>Date of Inspection: 05/12/2020</b>		<b>District: Muzaffarpur</b>
<b>Division: Muzaffarpur West</b>		<b>Length (km): 2.5</b>
<b>Name of the Road: sahebgang mahavir asthan - parapatti path</b>		
<b>Scheme/Programme:</b>	MAINTENANCE	
<b>Package No.:</b>	<b>Road Id No.: NEA220002543</b>	
<b>Status of the Project:</b>	<b>In Process of Agreement</b>	
<b>Work is a case of:</b>	<b>New Connectivity/Up Gradation/Maintenance</b>	
<b>Sl. No.</b>	<b>Parameters to be Checked</b>	<b>Remarks</b>
<b>1.</b>	<b>Pavement</b>	
a)	Road Junction Condition	N/A
b)	Condition of Surfacing	N/A
c)	Riding Quality	N/A
d)	Road Camber	N/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A
f)	Contraction Joints provided or not (CC Pavement)	N/A
g)	Compaction of flank/slop & rain cuts if any	N/A
<b>2.</b>	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	N/A
b)	Condition of Abutment & Wing Walls, Slab in RCC Culverts	N/A
c)	Condition of railings/slab/approach for Bridges	N/A
<b>3.</b>	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	N/A
<b>4.</b>	<b>Compliance History</b>	
a)	Status of ATR's & any others	NO

Overall Rating : **In Process of Agreement**

<b>Satisfactory (S)</b>	N/A
<b>Satisfactory but requires Improvement (SRI)</b>	N/A
<b>Unsatisfactory (U)</b>	N/A

  
(Signature)

**NAME: KISHORE KUMAR**  
**DESIGNATION: EXECUTIVE ENGINEER**