## FIELD INSPECTION REPORT

Date of Inc	spection: 05/1	2/2020 Die	trict: Muzaffarpur	
Date of Inspection: 05/12/2020 District: Muzaffary Division: Muzaffarpur West Length (km):2.65				
	ne Road: Gho	rijor Pul Dhanaiya - Parsa Teura		
Scheme/Programme:		MAINTENANCE		
Package No.:		Road Id No.: NEA220002564		
Status of the Project:		In Process of Agreement		
Work is a		New Connectivity/Up Gradation/	Maintenance	
Sl. No.		Parameters to be Checked	Remarks	
1.	Pavement			
a)	Road Junction	on Condition	N/A	
b)	Condition of	f Surfacing	N/A	
c)	Riding Quality		N/A	
d)	Road Cambo	er	N/A	
e)		Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
f)	Contraction	Joints provided or not (CC Pavement)		
g)	Compaction of flank/slop & rain cuts if any N/A			
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting N/A		neluding its N/A	
b)	Condition of Abutment & Wing Walls, Slab in RCC Culverts		.CC Culverts N/A	
c)	Condition of railings/slab/approach for Bridges		N/A	
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
4.	Compliance History			
a)		tatus of ATR's & any others		

Overall Rating: In Process of Agreement

Satisfactory (S)	N/A
Satisfactory but requires Improvement (SRI)	N/A
Unsatisfactory (U)	N/A

(Signature)

NAME: KISHORE KUMAR

**DESIGNTION: EXECUTIVE ENGINEER**