

FIELD INSPECTION REPORT			
Date of Inspection :	05/12/2020	District : BHAGALPUR	
Division :	R.W.D WORKS Div. Nongachhia	Length (km) : 1.800 km	
Name of the Road :	PWD Road to Kaharu chowk		
Scheme/Programme :	Maintenance		
Package No. :		Road Id No. :	
Status of the Project :	Ongoing/Completed/Under Maintenance	Ongoing	
Work is a case of :	New Connectivity/Up gradation/Maintenance	Maintenance	
Sl. No.	Parameters to be checked		Remarks
1	Pavement		work not started
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Road Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culvert including its painting.		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3	Cross Drainage		
a)	Whether sign boards/informatory/cautionary Boards/ km & 200m stones/Pavements roads marking are provided and maintained. Informatory Board Fixed at Site.		Yes/No
4	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME : VIKASH KUMAR

DESIGNATION : Junior ENGINEER

Vikash Kumar
(Signature)
work section Bihpur