

FIELD INSPECTION REPORT

Date of Inspection :	05/12/2020	District :	BHAGALPUR
Division :	RWD WORKS Div. Nalgachhia	Length (km) :	2.800 Km
Name of the Road :	NH-31 Hario village to Bishu Baba Asthan		
Scheme/Programme :	Maintenance New Maintenance Policy 2018		
Package No. :		Road Id No. :	
Status of the Project :	Ongoing/Completed/Under Maintenance	ongoing	
Work is a case of :	New Connectivity/Up gradation/Maintenance	Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1	Pavement	work not started	S/U
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Road Quality		S/U
d)	Road Camber		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Conpaction of flank/slope & raincuts if any		Yes/No
2	Cross Drainage		S/SRI/U
a)	Condition of head walls in Hume pipe culvert including its painting.		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		
3	Cross Drainage		Yes/No
a)	Whether sign boards/informatory/cautionary Boards/ km & 200m stones/Pavements roads marking are provided and maintained. Informatory board fixed at site.		
4	Compliance History		NO
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

NAME: Narendra Kumar
DESIGNATION: Assistant Engineer

(Signature) Narendra Kumar
05/12/2020
सहायक अभियंता
ग्रा० कार्य वि०
कार्य अवर प्रमंडल, विहपुर