## FIELD INSPECTION REPORT

vicio:	DATE AT .	trict:- Sheohar.	
VISIOI	:-RWD, Works Div. Sheohar Lei	ngth (km):- 2.2(	okon
hama	f the Road:- Sy wahute Maladava ( Programme:- MAINTENANCE	bandh	
ckage		1717	
		ad Id No.:	
ork is	f the Project: Ongoing/Completed/Un a case of: New Connectivity/Up g	redetion/Mainten	Not St
No.	Parameters to be checked	d auation/ Mainte	Remarks
1.	Pavement Pavement	u	Kemarks
1)	Road Junction condition		S/U
)	Condition of Surfacing		S/U
()	Riding Quality		S/U
	Road Camber		S/U
_	Whether free from defects such as	visible cracks.	Yes/No
	exposed aggregates in case of CC Pave		
	Contraction Joints provided or not (C		Yes/No
	Compaction of flank/slope & raincuts		Yes/No
	Cross Drainage		8
74.	Condition of head walls in Hume including its painting	pipe culverts	S/SRI/U
	Condition of Abutments & Wing walls	s, Slab in RCC	S/SRI/U
	Condition of railing/slab/approach for	bridges	S/SRI/U
	Road Furniture		
V	Whether sing board/informatory/caut	ionary Board/	Yes/No
K	Km & 200m stones/Pavement road	marking are	_
	rovided and maintained		
	Compliance History		
	tatus of ATR's & any others	work is	

**Overall Rating** 

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

(Signature)

Name: - Ratash kumar

DESIGNATION: - Junious Engineer