FIELD INSPECTION REPORT

Date of Inspection: 06/12/2020			District: Jamus	
Division:			Length (km): 3.25 km	
lame of	the Road: 54	Khasan To		GSY RE
cheme/	Programme:	MAINTENANCE	100/100 119	99/
Package			Road Id No.: NEA22000	783
Work is a case of: New Connectivity/		Opgoing/Complete	mpleted/Under Maintenance tivity/Up gradation/ Maintenance	
		New Connectivity/		
Sl-No.		Parameters to	be checked	Remarks
1.	Pavement			guid élekking og a
a)	Road Junction condition			SAU
b)	Condition of Surfacing			_S/U-
c)	Riding Quality			-SAU-
d)	Road Camber			-SAU-
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			-Yes/No
f)	Contraction Joints provided or not (CC Pavement)			-Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Gross Drainas	e care and		
a)	Condition of head walls in Hume pipe culverts including its painting			- S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Fornitu	ie (Carlotte		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
	Compliance la	kiory		
a)	Status of ATR'	s & any others		

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	-

huh 2020

(Signature)

NAME:

DESIGNATION:

(Askok Kimus Anja) AE, RND, Laxmipus