FIELD INSPECTION REPORT

Date of Inspection: OG · 12 · 2020 District: Kallkam.			
Name of Road:		(Tema) Bagehhala To Kelabani	
Scheme/	Programme:	MAINTENANCE New maintenance po	licy.
Package No. Road ID No.			U
Status of	the Project:	Onging/Completed/Under Maintenance	
Work is a	case of:	New Connectivity/ Up Gradation/ Maintenance	
Sl.No		Parameters to be Checked	Remarks
1	Pavement	to the control of the second of the second of the second of the control of the second	and Anna Carre
a)	Road Junction Condition		NIA
b)	Condition of Surfacing		NIA
c)	Riding Quality		NIA
d)	Road Camber		HIA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		NIA
f)	Contraction Joints provided or not (CC Pavement)		NIA
g)	Compaction of flank/slpoe & raincuts if any		NIA
2	Cross Drainage		
a)	Condition of headwalls inn Humepipe culverts including its painting		NA
b)	Condition of Abutment & Wings walls, Slab in RCC culverts		NIA
c)	Condition of railings/slabs//approach for Bridges		NA
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.		4/10
4	Compliance History		
a)	Status of ATR & any	others	NA

Overall Grading:

Satisfactory (S)
Satisfactory but requires Improvement(SRI)
Unsatisfactory (U)

Name: Satish choudhouri

Degisnation Assistant Engineer:

R-W'D-Manihari

) | Signature | Signature