

FIELD INSPECTION REPORT

Date of Inspection: 04/12/2020		District: East Champaran
Division: Arera		Length (km): 2.600
Name of the Road: T-2 Kanchadwa chaur to Kanchadwa kushwaha		
Scheme/Programme: MAINTENANCE		
Package No.: MR-N/19-20 Arera 23		Read Id No.: 10108565
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Particulars	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
Bridges		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N/A
Road Markings		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
Other Particulars		
a)	Status of ATR's & any others	No

only for inform
OPAT
Available

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

464
05/12/2020
(Signature)

NAME: Harendra Sol

DESIGNATION: A.E. RWD
Arera