

FIELD INSPECTION REPORT

Date Of Inspection	2.12.2020	District	Bhojpur
Division - PIRo, Block- PIRo		Length (km):	1.50
Name of the Road:	PWD ROAD to Basawanola		
Scheme/Programme	MAINTENANCE		
Package No.:	RM/BH/PIR/19/0005	Road Id No.:	1484014181031826
Status of the Project :	Ongoing/Completed/Under Maintenance ✓		
Work is a case of :	New Connectivity/Up gradation/Maintenance ✓		
SI No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	✓ S/U	
b)	Condition of Surfacing	✓ S/U	
c)	Riding Quality	✓ S/U	
d)	Road Camber	✓ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No N.A	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N.A	
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N.A	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N.A	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N.A	
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No	
4	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	"S"
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Name: Sushil Kumar

Designation

Junior Engineer

(Signature)
02/12/2020