

# FIELD INSPECTION REPORT

Date Of Inspection		2.12.2020	District	Bhojpur
Division		works Division Piro, Black-Piro	Length (km): 7.600	
Name of the Road:		Amhala Pul to Biryapur & Ganpat Tola Salkhara, Buryapur Tola, Budhram Tola		
Scheme/Programme		MAINTENANCE		
Package No.:		RM/BH/PIR/19/002	Road Id No.: 14181031840	
Status of the Project :		Ongoing/Completed/Under Maintenance		
Work is a case of :		New Connectivity/Up gradation/Maintenance ✓		
SI No.	Parameters to be checked		Remarks	
1	<b>Pavement</b>		Work in progress	
a)	Road Junction condition		S/U	
b)	Condition of Surfacing		S/U	
c)	Riding Quality		S/U	
d)	Road Camber		S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		Yes/No	
f)	Contraction Joints provided or not (CC Pavement)		Yes/No	
g)	Compaction of flank/slope & raincuts if any		Yes/No	
2	<b>Cross Drainage</b>			
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U	
c)	Condition of railings/slab/approach for Bridges		S/SRI/U	
3	<b>Road Furniture</b>			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No	
4	<b>Compliance History</b>			
a)	Status of ATR's & any others			

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Name:

Sushil Kumar

22/12/2020  
(Signature)

Designation

Jr Engineer