## Date of Inspection: 04.12.2020 FIELD INSPECTION REPORT Markale gow District: WLE Name of the Road: Champatia lat park Karnamya totoi hatiq chank wia Ih Package No.: RM/WEYNAKIM/bolls Road Id No.: 3/889/03/903 New Connectivity/Up gradation/ Maintenance SI. No. Parameters to be checked 1. Payement Remarks a) Road Junction condition b) proporting Condition of Surfacing c) Riding Quality d) Road Camber Whether free from defects such as visible cracks, exposed e) aggregates in case of CC Pavement. MA f) Contraction Joints provided or not (CC Pavement) NA g) Compaction of flank/slope & raincuts if any MO 2 Cross Drainage a) Condition of head walls in Hume pipe culverts including its painting NA b) Condition of Abutment & Wing walls, Slab in RCC culverts NA Condition of railings/slab/approach for Bridges c) NA 3. Road Furniture Whether sign boards/informatory/cautionary Board/km & 200m a) stones/Pavement road markings are provided and maintained 4 Compliance History Status of ATR's & any others a)

Overall Rating

Satisfactory (S)	2
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-

(Signature)

NAME: JAY PRAPASH RAM

DESIGNATION: JE