

FIELD INSPECTION REPORT

Date of Inspection : 04.12.2020		District: W. Champaran
Division : Nandkatiaganj		Length (km): 7.95 km
Name of the Road: Sikta to Ekday		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance ongoing		
Work is a case of: New Connectivity/Up gradation/ Maintenance maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	ongoing S/U
b)	Condition of Surfacing	ongoing S/U
c)	Riding Quality	ongoing S/U
d)	Road Camber	ongoing S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NP Yes/No
f)	Contraction Joints provided or not (CC Pavement)	NP Yes/No
g)	Compaction of flank/slope & raincuts if any	NP Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	NP S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NP S/SRI/U
c)	Condition of railings/slab/approach for Bridges	NP S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	NP Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	8
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

NAME: Chandradeo Pd

DESIGNATION: JE

(Signature)
04/12/20
JE