FIELD INSPECTION REPORT

Date of I	nspection: 07/12/2020 D	istrict: Jancu'	
Division	: Janu' L	ength (km): 7.10	
Name of	the Road: Sikandra Nawado	PWD Road to Balad	<u>'b</u>
Scheme/	Programme: MAINTENANCE		
Package	1 1 1 1 1 20 1 3 4 1 1 2 1 3 4	ond Id No.: 28411032	491
	the Project: Ongoing/Completed/Un		
	a case of: New Connectivity/Up g	The second secon	
Sl. No.	Parameters to be	WITCH S.	Remarks
1.	Pavement		
a)	Road Junction condition		√8/U
b)	Condition of Surfacing		√8 /U
c)	Riding Quality		√8 /U
d)	Road Camber		√8/U
e)	Whether free from defects such a aggregates in case of CC Pavement.	as visible cracks, exposed	Yes/No N/A
- f)	Contraction Joints provided or not (CC	Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts is	f any	Yes/No
2.	Cross Draininge	The state of the s	A Marie Control of the Control of th
a)	Condition of head walls in Hume pipe	culverts including its painting	S/SRI/U work has not been
b)	Condition of Abutment & Wing walls,	Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for	Bridges	_S/SRIAU
3.	Road Farniture		
a)	Whether sign boards/informatory/cau stones/Pavement road markings are pro	ntionary Board/km & 200m ovided and maintained	Yes/No
4,1	Compliance History	La pare	
a)	Status of ATR's & any others		NIA

Overall Rating

Satisfactory (S)	's'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	× .

NAME:

DESIGNATION:

W.D. (W.) Division

Signature