

FIELD INSPECTION REPORT

Date of Inspection : 07/12/2020		District: Jamui	
Division : Jamui		Length (km): 0.572 Km	
Name of the Road: Malaypur Barhad Road To Behra			
Scheme/Programme: MAINTENANCE			
Package No.: MR-N/19-20/Jamui-1	Road Id No.: 28411032600		
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of: New Connectivity/Up gradation/ Maintenance			
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	SAU	N/A
b)	Condition of Surfacing	SAU	N/A
c)	Riding Quality	SAU	N/A
d)	Road Camber	SAU	N/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No	N/A
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	N/A
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	N/A	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Work not started.

Ashe
07/12/20

(Signature)

NAME:

Ashe Kumar Anja

DESIGNATION:

AE. RWD, Laxmipur