

FIELD INSPECTION REPORT

Date of Inspection :	07/12/2020	District:	Jammu
Division :	Jammu	Length (km):	
Name of the Road:	Jammu Khasappur PWD road to Karmal Ratanpur		
Scheme/Programme:	MAINTENANCE Road via Daska Tataria		
Package No.:	MR-N/19-20/Jammu-17	Road Id No.:	28411032612
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SAU N/A
b)	Condition of Surfacing	S/U N/A
c)	Riding Quality	SAU N/A
d)	Road Camber	SAU N/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No N/A
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Work not started

(Signature)
07/12/2020

(Signature)

NAME:

DESIGNATION:

(Ashish Kumar Arora)
AE, RWD, Ladwara